ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0178, W0099, W0150, W0164, W0162, WA150, W0133, W	NA, Vinayaka Lyt 4th Crs	BHEL Mini Colony, Vijayalakshmi Layout, Muneshwara
Segment No.	**Total Length (m)**	
13/C-W0178/S021132	668.38	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	94.77	77.515481	13.053664	77.515196	13.052854	BHEL Mini Colony	Main Road
2	94.03	77.515228	13.053779	77.514950	13.052974	Vinayaka Layout	4th Cross
3	91.56	77.515025	13.053815	77.514724	13.053042	Vinayaka Layout	5th Cross
4	87.26	77.514998	13.054414	77.515765	13.054176	Vijayalakshmi Layout	Cross roada
5	28.76	77.516071	13.053915	77.516012	13.053661	Vijayalakshmi Layout	Cross road
6	45.49	77.515819	13.054137	77.515701	13.053742	Muneshwaranagar	Cross road
7	45.58	77.515566	13.054207	77.515422	13.053820	Muneshwaranagar	Cross road
8	54.43	77.515271	13.054314	77.515108	13.053849	Ravindranagar a	Cross roada
9	126.50	77.515017	13.054617	77.514609	13.053546	Ravindranagar a	cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Repairs of Culverts in Ward No.13, in Shettyhalli Sub Division.	2000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	Culvert
Tender	**Work Details**	**Job No. / Work Code**
Tender		013-17-000035
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/69/2017-18	11/05/2017	

Defect Liability Period From

	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
- 11/05/2017	30/06/2017	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Sri N Shivananda		0.00
Phone No.	**E-Mail ID**	
9901829745		

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0178, W0099, W0150, W0164,